DD/S 63 - 4384/ Approved For Release 2002/11/08 CTA-RDP84-00780R000100200003-8

25X1

16 October 1963

MEMORANDUM FOR:	Deputy Assistant Director, Production
THROUGH :	Chief, General Sciences Division, SI
FROM :	ESB/GSD/SI
SUBJECT :	Report of Inspection, NPIC, 11 October 1963
determine if a toxic chemicals or the handled dangerous condition or areas. Apparently the	
2. As a result of it can be concluded as	the inspection and based on the following analysis, follows:
hazardous condition	not appear to be an immediately dangerous or on which could cause loss of life except in some 25X1 egligence. Such negligence would be the intro-

SUBJECT: Report of Inspection, NPIC, 11 October 1963

25X1

25X1

e. There does not appear to be a problem in the room called "tank farm". This room is a floor above the photo laboratory rooms and contains several 300 gallon stainless steel sealable storage tanks plus several mixing vessels of about 150 gallons each. Here the various	
	25X1
3. A suggested solution to major existing problems would be a separate ventilating system taking in fresh air and exhausting the used air for one entire floor or area in which would be located all laboratory facilities and related air contaminating equipment.	
4. As concerns the photographic laboratory, there is a trained, graduate chemist with over 6 years industrial experience in photographic chemistry laboratory work. Although new on his present job, he is in a position to observe and make appropriate recommendations on	25X1
the chemical versus health problem in the photo laboratory.  there has called attention to some areas requiring ventilation and	25X1
action should be taken in this regard. Chief Logistics Branch and Security Officer, were most helpful. security safety officer was also extremely helpful and also has proper recommendations to make looking to safety on a longer range basis.	25X1 25X1
	25X1